






PICTURE

#3

#1 V.C. pipe with
ROOT OBSTRUCTION
REMOVED/REPLACED




#2 SHOWS NEW PVC pipe
REPLACED TO THE
MANHOLE (10' new)

#3 UPSTREAM FERNO
Rubber COUPLING
REPLACED



PICTURES
#1 + #2 - EVIDENCE THAT
SSO had occurred.

#3 + #4 show location
of SSO + downstream
MANHOLE off of Atlantic
Ave.



PICTURE

#1 #76 FOUNDATION

#2 DOWNSTREAM MANHOLE

"Looking up towards area
where SSO had occurred."


#3 Looking FROM MANHOLE
TOWARDS ATLANTIC AVE
#76 is to the right.

Hull Waste Water



Atlantic, Ocean

Hull Waste Water



APRIL 2013

